

Instructions for shipment of specbos and spectral devices for recalibration at JETI



Please follow the hints below to make the procedure easy and effective:

- Ship the unit(s) directly to:
JETI Technische Instrumente GmbH
Göschwitzer Str. 48
D-07745 Jena
Germany
- Declare the shipment as temporary export and use the appropriate customs documents
- Use the customs code number 9027 3000 (also known as TARIC Code)
- Select consignee rather than exporter for duties and taxes payable by ... in the commercial invoice
- Use a small value for the returned device, e.g. EUR 500, to make the customs procedure easier
- If you add your own transport carrier account number, we will use it for the reshipment
- Don't forget to add the diffusor cap, if the spectral irradiance calibration shall be included
- Use the original transport box for the shipment
- If there arised any question or problem during use of the instrument, please add a description to the shipment