specbos 25x1 Firmware Changelog

V1.2.2

- Initialisation of ADC at firmware start revised, as otherwise signal could be disturbed

V1.2.0

- Adaptation revised
- Power management revised
- Output of the radiometric spectrum in the restricted wavelength range did not work correctly -> fixed
- Support for up to 16 calibration files
- USB functions revised, resulting in better connection stability and improved error handling

V1.0.2

 with sync mode switched on, the measurement could be overdriven if the integration time was shorter than the period duration -> fixed

V1.0.1

in special cases, the subsequent measurement could fail despite successful adaptation -> fixed

V1.0.0

First release of specbos 2501 firmware